
DIXIE LAKE SEDIMENT CHARACTERISTICS MAP

OAKLAND COUNTY, MICHIGAN T.4N, R.8E

LEGEND
-5— Contours



Note: Hydro-acoustic depth measurements conducted in Sept. 27, 2017. Bathymetric data processed by Navico.

Lake shoreline digitized from 2015 aerial orthodigital photography (Source: SEMCOG)

October 2017

rogressive ae

1811 4 Mile Rd NE | Grand Rapids, MI 49525 | 616-361-2664 | www.progressiveae.com